-	0
1	1
6 0	1/

Work Order: DART AEROSPACE LTD D2889 Part Number: Description: Fwd Crosstube Qty: Drawing: D2889 Rev. B; D6005 Rev. A Page 1 of 2

- 1	1.08		Ву	Date	Qty
tep	Location	Procedure	VIL	03.09.19	19
1	DC	Issue Traveller Dwg. not required PF 02.11.05	7X	03.09.11	11
Sterry		Dug not required	PER !		1167
2	PG *	Issue P/O:		"在生产业 "	
	· 集 // ()	1			
	F-1881	non/44) \ Coamless all lill lull tube		1 1	
	f- other	I was the leave the state of th	die .	Marin Com	
DIE		A) Minimum tensile viela streligin – ooksi	1	13 191.22	114
	- 15	- Material certification required	X		11
	RG	To and inspect for transit dalliage	1	04-01-05	22
3	NO		0	YI A	10
4	QC6	Inspect dimensions as per Dwg D6005 and check 180' length	11	0402.11	1
			1	1.02.11	120
5	FP	Acid etch and alodine as per QSI 005 4.1	1	0102 11	1
1		Inside and outside of tube	15	Jan State of	
6	LG	Bend as per Dwg D2889 and Folio FT001	The state of		3
1		Sign Page 2 Inspect dimensions per Dwg D2889	J. of	A CHAIN THE	
7	QC6	Inspect differsions per 21.5	1 6		
100	1 12 130 14 2012	Sign Page 2 Deburr and Polish	Clerky.		
8	LG	21 22 2		100	DE SE
	FP	Acid etch and alodine as per QSI 005 4.1		1	7
9		Inside and outside of tube	nn	05030	11
-12		Sign Page 2	- //	7	
10	QC5	Inspect work to Step 9	1	-05.03.0-	1
		Sign Page 2	AL	1	- 1
11	ST	Identify and stock	C	2 05/03/0	1 1
18		A THE RESERVE OF THE PARTY OF T			
12	AC	Cóst / part: /58925	0	105.05-1	0 1
1	4. 3. 39	Close W/O 739,00	ck	1	(2)
13	DC	Close W/O 739,00	17	\$ 05.05.	WI
1		IIISPECI LOVOIL	4 1	ad Py An	

12/ 14	TA ALLE		Revised By	Approved
Rev	Date	Change	DM	
A	99.05.31	New Issue, ECN 200	EC	A 1 1 1 1 1 1
В	00.04.11	Remove Painting step	KJ 134	1
С	02.10.18	Re-format; Added spec	THE WAY	

11	Aer	os	pace	Ltd
----	-----	----	------	-----

NOTE: Date & initial all entries H:Admin-QA\ISO\forms\w/oncB.doc

Work Order:		WORK ORDER CHANGES				i.e	
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Manuf / Design Mgr	Approval QC Inspector
E.K. *							
04		· ·					

NCR 1960	66	WORK ORDER NON-CONFORMANCE										
DATE STEP		Description of NC section A	Intial	Corrective Action Section B	Verification Section C	Approval Design Mgr	Approval QC Inspector					
OH 02-11	hl	Omensiones should be actual dimen of 2.750 OD 42.741 00 of 2.000 ID 62.000 1D 0.375 Wall 1. Wall	A	occeptable only 0.003" out of Ideana used on Extended gear find xhibes Ope.	Date 8 09 02-11	010711	04.02.11	8.				
	6	TUBE IS Overyout) 	(par 06005, 00 15 ±0.006) wall 15 ±0.015) SCRAP	J.05.11	NA	#4.05.11					
		*		egy ² .:								

PAR#:	Fault Category:	DQA:	Date:		
5		QA: N/C Closed:	Date:		

THE SERVICE LTD	Work Order:	19666
JART AEROSPACE LTD	50.0	N 18
5 10 - the	Part Number:	D2889
Description: Fwd Crosstube		
D DOODE Boy A	Qty:	19
Drawing: D2889 Rev. B; D6005 Rev. A		Page 2 of 2

							_	14	1	J	K	L
W/O Step	Α	В	С	D	E	-	G	Н			CTARA	3
6	8	EP OHOSTI	(A)	DP	22 04/04/	N 05-2-30	05:33		V			
7	100	A 64.05.11	4 05-11	of what	Silidi	-H-	050303				je .	
8	2				- 111 Jes		05-37	Ž.			Ŷ*	100
9	S											V.
10										75 A. A.	7	

#D for D705-596-101 is 119.125" angles 57,57°